

Pro Tools® Hardware and Software Compatibility Guide for Lynx Aurora & Hilo Converters



HD-X / HD NATIVE

Hardware: HD Native and HDX with Aurora/HD and Hilo with LT-HD Installed
Software: ProTools 8.1 through current versions, OS X or Windows

Compatible with LT-HD firmware revision 11.

PCI / PCI EXPRESS

Hardware: AES16, AES16e, LynxTWO, L22, E22, E44
Software: ProTools 9 through current versions, OS X or Windows

Compatible, with current drivers and firmware.

USB / THUNDERBOLT

Hardware: Aurora/USB, Aurora/TB, Hilo/USB and Hilo/TB
Software: ProTools 9 through current versions, OS X or Windows

Aurora/USB and Aurora/TB on OS X are fully compatible.

Hilo/USB and Hilo/TB on OS X are fully compatible.

With Windows and Aurora/TB or Hilo/TB, current drivers are required.